

Parametersätze für Frequenzumformer Nowforever D100
S1 R5B Fräse X6-1500USB von Carving-CNC erstellt von
M45t3r Of H4rdc0r3

Funktionsgruppe P0 -									
	Wert		Wert		Wert		Wert		Wert
000	1	023	10.00	046	3.00	069	10.00	092	0
001	0	024	400.00	047	0	070	11.00	093	0
002	2	025	2	048	1.00	071	12.00	094	15.0
003	2	026	3	049	2.00	072	13.00	095	15.0
004	400.00	027	0	050	0	073	14.00	096	15.0
005	5.00	028	1.00	051	0	074	15.00	097	15.0
006	0	029	0	052	0	075	0	098	15.0
007	400.00	030	0	053	15.0	076	0	099	15.0
008	0	031	0	054	15.0	077	0	100	15.0
009	8.0	032	0	055	1	078	0	101	15.0
010	8.0	033	0	056	2	079	0	102	0
011	6.0	034	0	057	0	080	0	103	15.0
012	400.00	035	100.00	058	0	081	0	104	15.0
013	1.0	036	150.0	059	0	082	0	105	220.0
014	0	037	130.0	060	250.00	083	0	106	0
015	0	038	125.0	061	150.00	084	0	107	30.0
016	1	039	0	062	350.00	085	0	108	7
017	24	040	0	063	100.00	086	0	109	8
018	25	041	0	064	300.00	087	0	110	1
019	26	042	0	065	200.00	088	0		
020	0	043	0	066	400.00	089	0		
021	0	044	0	067	8.00	090	0		
022	0	045	0	068	9.00	091	0		
Funktionsgruppe P1 -									
	Wert		Wert		Wert		Wert		Wert
000	0	001	0						
Funktionsgruppe P2 -									
	Wert		Wert		Wert		Wert		Wert
000	0								
Funktionsgruppe D0 -									
	Wert		Wert		Wert		Wert		Wert
000	4	001	4	002	4				
Funktionsgruppe D1 -									
	Wert		Wert		Wert		Wert		Wert
000	1500	002	3	004	220.0				
001	41182	003	1.5	005	8.0				
Funktionsgruppe D2 -									
	Wert		Wert		Wert		Wert		Wert
000	0	004	0.0	008	3.00	012	0		
001	400.00	005	315	009	10.00	013	0		
002	0.00	006	0.0	010	400.00	014	0		
003	0.0	007	10	011	400.00	015	0		
Funktionsgruppe D3 -									
	Wert		Wert		Wert		Wert		Wert
000	0	002	10.0	004	0.00	006	510		
001	0	003	0.00	005	510				